

SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO :
FROM :
ACTION:
INFO :

IN: 91947

ops, u D

TO SECRET 260819Z CITE [REDACTED] 1381
PRIORITY [REDACTED]
[REDACTED]

CITE 25X1A
25X1A
25X1A

C216C/260230Z/385

SYSTEM 6

- 26/D/1011/65/37/34/1001/21
- SPOT CHECK NEAR END OF MISSION INDICATED THAT SYSTEM FUNCTIONED PROPERLY.

SYSTEM 9B

- 106
- NO ACTIVITY --SELF TESTED OK.

SYSTEM 12B

- 14/143/143
- NO ACTIVITY --SELF TEST OK.

SYSTEM 13C

- B-602
- REPEAT LIGHT FROM 0355 TO 0403Z. OVERHEAT LIGHT CAME ON AT 0500Z DUE TO PRESSURIZATION PROBLEM AND STAYED ON FOR REST

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

S E C R E T

PAGE-2 [REDACTED] 1381

IN: 91947

25X1A

OF FLIGHT. SELF TESTED OK.

OSCAR SIERRA

1. 3

2. NO ACTIVITY--SELF TESTED OK.

[REDACTED] SATISFACTORY

25X1A

RADIO AND NAVAIDS SATISFACTORY

UMY-20 C791--100 PERCENT

S E C R E T TOR: 26/0915Z NOV 66

S E C R E T